

# NOTICE OF ALTERATIONS

Date: November 26, 1999  
 Ref. No.: KM6-99-F005

Application : FCC  
 Name of Appliance : DOT PRINTER  
 FCC ID : ACJ5Z6KX-P3196

Enforcement Date : Scheduled for end of December 1999  
 Model No. : KX-P3196  
 Issued : February 16, 1999

Method Presently Employed	Alteration to be Introduced
<p>1.Print Circuit Board</p> <p>2.Control Panel ES Core is inserted to Control Panel FFC.</p> <p>3.Inlet Lead Two ES Cores are binded.</p>	<p>1.Print Circuit Board Secondary Print Circuit Board is changed.</p> <p>Please refer to attached sheet.</p> <p>2.Control Panel We will delete the ES Core.</p> <p>3.Inlet Lead We will delete two ES Cores.</p>