

### Photos of Radiation Measuring Setup

30MHz to 1GHz


Adapter + Battery Mode



x-axis



y-axis



z-axis







Battery Mode



x-axis



y-axis



z-axis







above 1GHz  
Adapter + Battery Mode




x-axis



y-axis



z-axis







Battery Mode




x-axis



y-axis



z-axis





### Photos of Conduction Measuring Setup

