



Bureau Veritas Consumer Products Services (H.K.) Ltd., Taoyuan Branch
香港商立德國際商品試驗有限公司桃園分公司

No.19,Hwa Ya 2nd Rd,Kwei Shan Hsiang ,taoyuan Hsien ,Taiwan, R.O.C.

桃園縣龜山鄉華亞二路19號

FAX: 886-3-3270892

A D T

http://www.adt.com.tw/ E-mail: service@adt.com.tw TEL: 886-3-3183232

May 08, 2012

Supersede request for FCC ID: ACQ-VAP2404

To Whom It May Concern:

We regret to inform you that exists 15.247 / 407 report on FCC website shall be removed. Since client decides to disable 5660MHz by software setting, so test report shall remove all information and test result of 5660MHz.Revised test reports will be provided to replace exist reports.

Please remove files as red mark.

OET Exhibits List

11 Matches found for FCC ID 'ACQ-VAP2404'

| View Attachment | Exhibit Type | Date Submitted to FCC | Display Type | Date Available |
|--|------------------------------|---------------------------------------|------------------------------|--------------------------------|
| Ad Hoc & DFS declaration | Attestation Statements | 04/20/2012 | pdf | |
| DFS band declaration | Attestation Statements | 04/20/2012 | pdf | |
| Confidentiality request | Cover Letter(s) | 04/20/2012 | pdf | |
| POA | Cover Letter(s) | 04/20/2012 | pdf | |
| Label location | ID Label/Location Info | 04/20/2012 | pdf | |
| Label sample | ID Label/Location Info | 04/20/2012 | pdf | |
| Operational description | Operational Description | 04/20/2012 | pdf | |
| RF exposure rev | RF Exposure Info | 04/20/2012 | pdf | |
| Test report 247 rev4 | Test Report | 04/20/2012 | pdf | |
| Test report 407 rev5 | Test Report | 04/20/2012 | pdf | |
| Test report DFS rev | Test Report | 04/20/2012 | pdf | |

Gary Chang

Technical Manager

Bureau Veritas Consumer Products Services (H.K.) Ltd., Taoyuan Branch

Tel: 886-3-3183232 ext. 1608

Fax: 886-3-3270892

Email: Gary.chang@tw.bureauveritas.com