



International Certification Corp. (全球檢測股份有限公司)

Tel : 886-3-271-8666

Fax : 886-3-318-0155

No.3-1, Lane 6, Wen 33rd Rd., Kwei Shan Hsiang, Tao Yuan Hsein 333, Taiwan (R.O.C.)

Nov. 19, 2014

Subject: Radiated emission data above 1GHz for FCC ID: ACQ-VAP3402 and ACQ-VAP3400

To Whom it may concern:

RF part is identical to FCC ID: ACQ-VAP3402 and ACQ-VAP3400

The difference between above FCC IDs is only Lan port(s).

Power setting is same for above FCC IDS thus conducted measurement is performed for FCC ID: ACQ-VAP3402 only.

Radiated emission below 1GHz is performed for both FCC IDs but radiated emission above 1GHz is performed for FCC ID: ACQ-VAP3402 only.

Both FCC IDs share same radiated emission above 1GHz and test results of antenna port conducted measurement.

Best regards

Gary Chang , Manager

Report & Certification department

[Tel:+886-3-271-8628](tel:+886-3-271-8628)

Email:Garychang@icertifi.com.tw