



- *NOTE1. Wire color code. (B):large wires.
- 2. Shield should be effectively grounded at scanner unit.
- 3. Connector plug factory-wired.
- 4. Shield grounded thru connector case.

REV No.	MARK	DATE	REMARKS	REV-BY	APPRV

M	FR-7062	CODE No.			

APPRV	CHCKD	DSIGND	DRANN	TIT	INTERCONNECTION DIAGRAM

DWG No.	03-142-6001-0	SHEET	1/1

FURUNO ELECTRIC CO., LTD.