

#### 4 Photographs of Terminal Unit IB-585 for Furuno SSB Radiotelephone FS-1575

- 4.1 Outside View
- 4.1.1 Front View



4.1.2 Rear View (showing Name Plate (ID Label))




4.1.3 ID Label (Name Plate)



4.2 Inside View


4.2.1 Inside View (with Rear cover removed, showing TERMCPU 16P0283, SD-USB 16P0289, TERMPWR 16P0287, and PWR-C 16P0214 Boards)




4.2.2 Inside View




4.2.3 Inside View (with PCBs removed)



4.2.4 Inside View (showing Back of chassis plate, and LCD module)




4.2.5 Inside View (showing Back of Front Panel, and SW Board 16P0212)






4.3 PCBs

4.3.1 TERMCPU Board 16P0283 Front side







4.3.3 TERMPWR Board 16P0287 Front side




4.3.4 TERMPWR Board 16P0287 Rear side




4.3.5 SD-USB Board 16P0289 Front side




4.3.6 SD-USB Board 16P0289 Rear side




4.3.7 PWR-C Board 16P0214 Front side



4.3.8 PWR-C Board 16P0214 Rear side



4.3.9 SW Board 16P0212 Front side



4.3.10 SW Board 16P0212 Rear side

