


Furuno Labotech International Co., Ltd. Document number: FLI 01-10-045

Date of issue: 5 January 2011






Furuno Labotech International Co., Ltd. Document number: FLI 01-10-045

Date of issue: 5 January 2011

2.4 Inside top view (with shield cover for IF Board 03P9404 removed.)






Furuno Labotech International Co., Ltd. Document number: FLI 01-10-045

Date of issue: 5 January 2011

Photographs of the Antenna unit with the Transceiver RTR-057A included for Furuno Marine Radar MODEL 1835

3 PCBs


3.1 MD Board MD9208 and RRV Board 03P9317 front side





Furuno Labotech International Co., Ltd. Document number: FLI 01-10-045 Date of issue: 5 January 2011

3.2 MD Board MD9208 rear side





Furuno Labotech International Co., Ltd. Document number: FLI 01-10-045

Date of issue: 5 January 2011

3.3 IF Board 03P9404 and PWR Board PTU-9335 front side

