Furuno Labotech International
Report no.: FLI 12-98-029




Photo 10.6 Processor Unit Right Side View (cover removed) (showing PSP board (02P6223))

Furuno Labotech International
Report no.: FLI 12-98-029




Photo 10.7 Processor Unit Left Side View (cover removed)
(showing RPW board (02P6224))

Furuno Labotech International

Report no. : FLI 12-98-029




Photo 10.8 Processor Unit Front View (cover removed)

Furuno Labotech International

Report no.: FLI 12-98-029




Photo 10.12 Radar Antenna Unit Inside View (for 48 rpm set (RSB-0073))
(Transceiver Module removed)

Furuno Labotech International

Report no.: FLI 12-98-029




Photo 10.13 Transceiver Module (RTR-059) Top View (showing Magnetron and Circulator)

Furuno Labotech International

Report no.: FLI 12-98-029




Photo 10.14 Transceiver Module (TRT-059) Bottom View (showing MD board (03P9235))