

Date of issue: 22 September 2010

# Photographs of the Transceiver Unit RTR-081A for Furuno Radar FAR-2827W 1 Internal View

1.1 Top cover removed (showing TB Board 03P9349 (lower) and Transceiver module (upper))





Date of issue: 22 September 2010

1.2 TB Board 03P9349 and Shield cover removed (Showing PWR Board 03P9348 on Transceiver Module)





Date of issue: 22 September 2010


### 1.3 Transceiver Module removed





Date of issue: 22 September 2010


1.4 Transceiver Module (Showing PWR Board 03P9348 (left) and RFC Board 03P9346 (right))





Date of issue: 22 September 2010

### 1.5Transceiver Module (Right side, PWR Board removed)





Date of issue: 22 September 2010


## 1.6 Transceiver Module (Front side)





Date of issue: 22 September 2010


# 1.7 Transceiver Module (Front cover opened, showing IF\_AMP Board 03P9335)





Date of issue: 22 September 2010

1.8 Transceiver Module (IF\_AMP Board 03P9335 removed, showing MIC RU-9601)





Date of issue: 22 September 2010


# 1.9 Transceiver Module (Bottom side)





Date of issue: 22 September 2010

1.10 Transceiver Module (Bottom cover opened, showing Pulse Transformer (lower left) and Magnetron (lower right))





Date of issue: 22 September 2010

# 1.11 Transceiver Module (showing MD Board 03P9244)

