



Icom Inc.
1-1-32, Kamiminami, Hirano-ku, Osaka 547-0003 Japan.
Phone : 06 6793 5302 Fax : 06 6793 0013
e-mail: world_support@icom.co.jp

Date: February 07, 2012

Federal Communications Commission
Authorization & Evaluation Division
7435 Oakland Mills Road
Colombia, Maryland 21046

To Whom It May Concern

Subject: Class2 permissive change
Model: IC-F1721/F1721D, IC-F1821/F1821D
FCC ID : AFJ278100

Dear Sir/Madam,

This is to inform you that there is class 2 permissive change on IC-F1721/F1721D and IC-F1821/F1821D to change its feature.

The contents of this change are,

Adding equivalent PA module from different manufacturer due to the parts supplying problem by original manufacturer, and ICOM wish to have an option to source this PA module from either supplier.

A parts change.

Please find attached the "difference of parts" about hardware update for details.

Thank you for your attention to this matter.

Icom Incorporated

Takayuki Watanabe
General Manager of Quality Department