



Icom Inc.
1-1-32, Kamiminami, Hirano-ku, Osaka 547-0003 Japan.
Phone : 06 6793 5302 Fax : 06 6793 0013
e-mail: world_support@icom.co.jp

March 12, 2008

Federal Communications Commission
Authorization & Evaluation Division
7435 Oakland Mills Road
Colombia, Maryland 21046

SUBJ. : Class2 permissive change
FCC ID : AFJ289300

To Whom It May Concern;


This is to inform you that there is class 2 permissive change on IC-F3161 to change its feature. The contents of this change is in attached documents.

The modified points are CPU and related parts, change design of RX IF filter circuit and MIC audio circuit. There are some minor change on trace of PC board, but there is no modification on RF circuit design and trace of RF PC board. In addition, this modification does not affect SAR measurement result. This change does not affect to the following specifications.

- 1) Radio frequency and RF output power;
- 2) Radio frequency circuitry;
- 3) Emission mode;

Thank you for your attention to this matter.

Icom Incorporated,



Yoshiteru Yano

General Manager of CS Department