



Icom Inc.
1-1-32, Kamiminami, Hirano-ku, Osaka 547-0003 Japan.
Phone : 06 6793 5302 Fax : 06 6793 0013
e-mail: world_support@icom.co.jp

Date: September 12, 2012

Federal Communications Commission
Authorization & Evaluation Division
7435 Oakland Mills Road
Colombia, Maryland 21046

To Whom It May Concern

Subject: Class2 permissive change
Model: IC-F4161T/S/DT/DS
FCC ID : AFJ289402

Dear Sir/Madam,

This is to inform you that there is class 2 permissive change on IC-F4161T/S/DT/DS to change its feature.

The contents of this change are a final AMP and some parts.

Please find attached the "difference of parts" about hardware update for details.

Thank you for your attention to this matter.

Icom Incorporated

A handwritten signature in cursive script, appearing to read 'H. Fujishima'.

Hideji Fujishima
General Manager of Quality Department

IC-F4161D Difference Parts List

RF Unit

REF No.	OLD	NEW
Q601	RD07MVS2-T112 *	RD07MUS2B-T112
L610	-	ELJRE 1N2ZF 1.2N
R619	ERJ3GE-JPW	-
R621	27K ERJ2GE	18K ERJ2GE
C620	2P C1608 CH B	3P C1608 CH B
C624	39P GQM18 CH	27P GQM18 CH
C643	22P C1005 CH	-

MAIN-A Unit

REF No.	OLD	NEW
R41	15K ERJ2GE	18K ERJ2GE
C75	4P C1005 CH B	5P C1005 CH B