

Icom Inc.

1-6-19,Kamikuratsukuri,Hirano-ku,Osaka Japan. Phone: +81 6 6793 8424 Fax: +81 6 6793 3336 e-mail: world\_support@icom.co.jp

URL: http://www.icom.co.jp/world

Date: July 10, 2013

## To Whom It May Concern

Subject:

**Attestation Letter** 

Applicant:

Icom Incorporated

Product:

**UHF H.H transceiver** 

Model:

IC-F4230DT/DS

FCC ID:

AFJ352202

Dear Sir/Madam,

For Part 90 frequency user, the radio is disabled 25kHz mode by radio firmware at factory in order to comply with FCC mandate for part 90 frequencies.

Best regards

Icom Incorporated

A Tryish Hideji Fujishima

General Manager of Quality Assurance Department