

iCOM

Model: ID-4100A


FCC ID: AFJ386600

IC: 202D-386600 HVIN: 386600-01

Icom Inc.

MADE IN JAPAN

SERIAL NO. 00000000



This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:

(1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

WARNING: MODIFICATION OF THIS DEVICE TO RECEIVE CELLULAR RADIOTELEPHONE SERVICE SIGNALS IS PROHIBITED UNDER FCC RULES AND FEDERAL LAW.



ICOM Model: ID-4100A
FCC ID: AFJ386600
IC: 2020-386600 HVIN: 386600-00
ICOM Inc. MADE IN JAPAN

SERIAL NO. 00000304



This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

WARNING: MODIFICATION OF THIS DEVICE TO RECEIVE CELLULAR TELEPHONE SERVICE SIGNALS IS PROHIBITED UNDER FCC RULES AND FEDERAL LAW.

Contains FCC ID : VIYHRM1016
Contains IC : 7305A-HRM1016

C-18101



機構図番 : 49249 (CF)
テトロン銀シール50 μ P.Pマツト
裏糊 : (株)リコー消銀マトリックス
黒地銀文字