

	360 Herndon Parkway, Suite 1400	Work Order number	2001326
	Herndon, VA 20170	FCC	Part 15.247
	<a href="http://www.rheintech.com">http://www.rheintech.com</a>	Industry Canada	RSS-210
		FCC ID	AFJAP-12
		M/N	AP-12

**APPENDIX N: INTERNAL PHOTOGRAPHS**





**PHOTOGRAPH 11: TOP VIEW MAIN PCB WITH SHIELD**

	360 Herndon Parkway, Suite 1400	Work Order number	2001326
	Herndon, VA 20170	FCC	Part 15.247
	<a href="http://www.rheintech.com">http://www.rheintech.com</a>	Industry Canada	RSS-210
		FCC ID	AFJAP-12
		M/N	AP-12



**PHOTOGRAPH 12: BOTTOM VIEW MAIN PCB WITH SHIELD**

	360 Herndon Parkway, Suite 1400	Work Order number	2001326
	Herndon, VA 20170		FCC Part 15.247
	<a href="http://www.rheintech.com">http://www.rheintech.com</a>	Industry Canada	RSS-210
		FCC ID	AFJAP-12
		M/N	AP-12




**PHOTOGRAPH 13: TOP VIEW MAIN PCB WITHOUT SHIELD**





360 Herndon Parkway, Suite 1400 Herndon, VA 20170 <a href="http://www.rheintech.com">http://www.rheintech.com</a>	Work Order number FCC Industry Canada FCC ID M/N	2001326 Part 15.247 RSS-210 AFJAP-12 AP-12
---	--	--



**PHOTOGRAPH 14: BOTTOM VIEW MAIN PCB WITHOUT SHIELD**