
TRANSIENT FREQUENCY BEHAVIOR FOR 12.5 kHz CHANNEL SPACING

PLOT # 31

FCC ID: AFJIC-F620-1


TRANSMITTER WAS TURNED OFF, NO MODULATION



PLOT # 32 FCC ID: AFJIC-F620-1

TRANSIENT FREQUENCY BEHAVIOR FOR 12.5 kHz CHANNEL SPACING


TRANSMITTER WAS TURNED ON, NO MODULATION



SUREMENTS PLOT # 33 el IC-F620-1 FCC ID: AFJIC-F620-1

TRANSIENT FREQUENCY BEHAVIOR FOR 12.5 kHz CHANNEL SPACING

TRANSMITTER WAS TURNED OFF, MODULATION: FM WITH 1 KHz SINEWAVE SIGNAL



PLOT #34 FCC ID: AFJIC-F620-1

TRANSIENT FREQUENCY BEHAVIOR FOR 12.5 kHz CHANNEL SPACING

TRANSMITTER WAS TURNED ON, MODULATION: FM WITH 1 KHz SINEWAVE SIGNAL

