

January 24, 2011

Ritron Inc. 505 West Carmel Dr. Carmel, IN 46032

Timco Engineering Inc. 849 NW State Road 45 Newberry, Florida 32669

REFERENCE: JOB 119UC11

Dear Sir/Madam:

In response to the following request dated 1/20/2011:

Based upon our review of this application we have the following questions:

1. TEST SETUP PHOTOS: We did not receive any test setup photos for this filing. Please send them at your earliest convenience. Thank you.

For your reference, I have re-submitted the RQT-451\_TestRpt.pdf document originally sent with this application. Page 3 of this document contains a photograph of the Ritron Test Site.

Sincerely,

Michael A. Pickard Project Engineer

Michael a. Pickard

Ritron, Inc.

505 W. Carmel Drive • Carmel, IN 46032-7564 P.O. Box 1998 • Carmel, IN 46082-1998

Ph: 317-846-1201 Fax: 317-846-4978 Email: ritron@ritron.com Web Site: www.ritron.com