

TYPE OF EXHIBIT: Part 15 Label
FCC PART: 15.19(a)(3)
MANUFACTURER: RITRON, INC.
505 West Carmel Drive
Carmel, IN 46032
MODELS: RQA-1B, RQA-4B
TYPE OF UNIT: 433.92 MHz Call Button Transmitter
FCC ID: AIERIT35-433
DATE: October 22, 2013

Pursuant to CFR 47 Part 15.19(a)(3) a label with the following Part 15 warning statement will be placed on the RQA-1B/4B enclosure.

The Part 15 warning statement is included on the FCC ID label. The FCC label is located on the inside of the case front and is readily visible when the battery is initially installed, and any time the battery is replaced.

This statement will also be included in the product instruction manual.

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions:
(1) This device may not cause harmful interference, and
(2) this device must accept any interference received, including interference that may cause undesired operation.

Signed: Michael A. Pickard
Michael A. Pickard - Project Engineer



Photo showing location of FCC ID label with Part 15 Warning