

Rockwell
Collins

RECEIVER-TRANSMITTER, HF
TYPE NO. HFS-2100 WT 16.6 LB

PNR 8223334040FC200

Rockwell Collins, Inc.
Cedar Rapids, IA 52498 USAMFD Melbourne, FL

MFR 1BSP7 DMF 032017
SER 4V49D

MODS	1	2	3	4	5	6	7	8	9	10	11	12	13	14	
15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30
31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46
47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62
63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78
79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94
95	96	97	98	99	100	101	102	103	104	105	106	107	108	109	110
A	B	C	D	E	F	G	H	J	K	L	M	N	P	R	T

CAUTION:
THIS EQUIPMENT
REQUIRES FIELD
LOADABLE SOFTWARE.
ENSURE CORRECT
SOFTWARE IS LOADED.
REFER TO AMM

LRU STATUS

KEY INTERLOCK

CONTROL FAIL



MON




TEST




HFS-2100

PHONE

MIC





CAUTION
REPLACE COVER BEFORE
REPLACING COMPONENTS
OR WIRING

CAUTION

EXPERIMENTAL FLIGHT TEST ONLY
ENGINEERING MOD STATUS
PROJECT **HFS-2100**
CPN **B22534040FC200** S/N **4V49D**
EQUIPMENT TYPE **HFS-2100**
PRODUCTION / SERVICE CENTER
FC110
FC120
ENG LAB / ENG PARTS

This device is not to be used
without the approval of the Federal
Communications Commission.
This device is not to be used
without the approval of the Federal
Communications Commission.

