

USER'S MANUALS – EXHIBIT H

1.1 **MANUALS**

Rockwell Collins, Inc. does not supply an instruction book with the VHF-4000 transceiver. The transceiver is supplied to airframe manufacturers and airlines, and designed to meet the requirements of ARINC 716-8 and ARINC 750. Operating instructions are not necessary because the unit is part of a larger VHF communications system. Rockwell Collins does produce the VHF-4000 Component Maintenance Manual, a comprehensive installation manual which, pursuant to an agreement with the FCC staff, is available upon request but is not included in this electronic exhibit.