

SONY

Sony Corporation

1-7-1 Konan, Minato-ku, Tokyo, 108-0075 Tel +81-3-6748-2111

August 18, 2008

**Federal Communications Commission
Authorization and Evaluation Division
Equipment Authorization Branch
7435 Oakland Mills Road
Columbia, MD 21046**

Subject : Request for Class II permissive Change

FCC ID : AK8PSP3001

Original grant date : August 13, 2008

Applicant : Sony Corporation

To Whom It May Concern:

This is to request a Class II permissive change for FCC ID: AK8PSP3001, originally granted on August 13, 2008.

1. Although the circuit construction of WLAN module in Front-End is different.

The reasons are;

- (i) For mass production, they have to use various components otherwise there will be a lack of component.
- (ii) To cut down the cost in the future.


These change do not affect the RF characteristics of WLAN Module, and we can tell this is Class II modification by the data of the measurement.

Please refer attached "Theory of Operation" and "Block Diagram" and "Schematics" for details of these modifications.

This time, we performed the testing and confirmed that this device still meets the minimum requirements of the applicable rules of FCC. Please refer to the test report submitted with this application.

Thank you for your attention to this matter.

Sincerely yours,



Ikuji Abe

Director

Customer Satisfaction Global Head office
Sony Corporation