



8. SETUP PHOTOS

ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP



RADIATED RF MEASUREMENT SETUP – ABOVE 1 GHz


HEADSET - EUT AT X POSITION



HEADSET - EUT AT Y POSITION



HEADSET - EUT AT Z POSITION




HEADSET WORST CASE: EUT AT Z POSITION







RADIATED RF MEASUREMENT SETUP – BELOW 1 GHz





POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP – without USB Charging Cable





POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP – with USB Charging Cable





END OF REPORT