

MFA M. Flom Associates, Inc.
Global Compliance Center

3356 N. San Marcos Pl., Suite 107
Chandler, Arizona 85225-7176
(480) 926-3100, FAX: -3598
general@mflom.com
www.mflom.com

August 7th, 2000

FEDERAL COMMUNICATIONS COMMISSION
Via Electronic Filing

Applicant: KENWOOD COMMUNICATIONS CORP.
Equipment: FCC ID: ALH29373210 (Model: TK-760/762HG-1)
EA97614
Corres. Errol Chang 14219 May 24, 2000
Steve Dayhoff 15412 Aug 04, 2000

Gentlemen:

Since #14219 references numerical items and Corresp. 15412 uses alpha items, an attempt will be made to avoid confusion in our replies.

Corres.14219

Item 1. Attached please find revised analysis using 50% duty factor. This indicates safe distance at approximately 3 feet (1 meter) which 'matches' information in User Manual.

Item 2. According to the Applicant, the antenna installation is performed by the Dealer. The Dealer follows the antenna installation instructions shown in the Manual.

Item 3. Applicant's instructions to Dealer are to follow those in Manual.

Corres. 15412

1(a): Antenna gain is dBd, unity gain

1(b): See Item 2 above

1(c): 50% duty factor per revised Analysis.

Trust the foregoing and attached answers your questions.

Sincerely yours,



cc: Applicant: Joel Berger
mf;mgf - enc.

MORTON FLOM, P. Eng.

P.S. Steve: May we have your phone number. It does not seem to be on the current list. Thanks.