

INTERTEK TESTING SERVICE

Report No: 15071281HKG-001

Configuration Photographs

Worst-Case Radiated Emissions

(Front View)

Model: GMR3055-2CK



INTERTEK TESTING SERVICE

Report No: 15071281HKG-001

Configuration Photographs

Worst-Case Radiated Emissions


(Rear View)

Model: GMR3055-2CK



Configuration Photographs
Worst-Case Line-Conducted Emissions
(Front View)

Model: GMR3055-2CK




INTERTEK TESTING SERVICE

Report No: 15071281HKG-001

Configuration Photographs Worst-Case Line-Conducted Emissions (Rear View)

Model: GMR3055-2CK



INTERTEK TESTING SERVICE

Report No: 15071281HKG-001

Configuration Photographs

Worst-Case Line-Conducted Emissions

(Side View)

Model: GMR3055-2CK

