


INTERTEK TESTING SERVICE

Report No.: 15071281HKG-001

Equipment Photographs

Model: GMR3055-2CK

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15071281HKG-001

Equipment Photographs

Model: GMR3055-2CK

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15071281HKG-001

Equipment Photographs

Model: GMR3055-2CK

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15071281HKG-001

Equipment Photographs

Model: GMR3055-2CK

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15071281HKG-001

Equipment Photographs

Model: GMR3055-2CK

(Internal)



INTERTEK TESTING SERVICE

Report No.: 15071281HKG-001

Equipment Photographs

Model: GMR3055-2CK

(Internal)

