

Date: September 28, 1999

To: Federal Communications Commission
TYPE OF EQUIPMENT: Scanning receiver
FCC ID: AMWUB310

Subject: Compliance to Cellular Band Exclusion:

Pursuant to the requirements contained in Part 15.121 of the Commission's Rules, this scanning receiver does not have the capability of tuning the frequencies assigned to the Domestic Public Cellular Radio Telecommunications Service.

In this circuitry, this device is not readily alterable to restore the cellular band coverage because the inventory of frequencies contained within this band are not available in the microprocessor. Also, the microprocessor is fixed soldered and not easily removable.

In addition, the critical circuitry is "hardened" with a black epoxy that covers the area of the circuitry that might be modified to circumvent the design efforts referenced above.

Therefore, since the clipping of leads; or the installation of a simple component such as a diode, resistor, or a jumper wire; or the reprogramming of any semiconductor device contained within this unit cannot be accomplished using a special access code or a personal computer; This is to certify that the conditions mandated in part 15.121 have been met.

Warning statement: The warning statement per section 15.121 (f) of the FCC Rules will be permanently indicated on the equipment.

**WARNING: MODIFICATION OF THIS DEVICE TO RECEIVE CELLULAR
RADIOTELEPHONE SERVICE SIGNALS IS PROHIBITED UNDER FCC
RULES AND FEDERAL LAW.**

Uniden Corporation



Keizo Fujiwara,
Engineering Manager
Engineering Department