

Uniden America Corporation
6225 N State Highway 161.
Suite 300
Irving, TX 75038
817-858-3300
Fax: 817-858-3333



Date: December 15, 2020

To: TIMCO ENGINEERING, INC., An IIA Company
849 NW State Road 45
Newberry, Florida 32669


Subject: FCC Class II Permissive Change for
HVIN: BCD436HP, FCC ID: AMWUB376, IC: 513-UB376
Original FCC Grant Date: 11/06/2013
Original ISED Certification Date: 12/16/2013
Applicant: Uniden America Corporation

This is to request a Class II Permissive Change for HVIN: BCD436HP, FCC ID: AMWUB376 that was originally granted on 11/06/2013 and the ISED Certification IC: 513C-UB376 that was issued on 12/16/2013.

The major changes filed under this application are:

- Updated PLL circuits:
 - PLL IC/Buffer Amp: MB15F72/UPC274 (EOL) to LMX2430/BGA2802
 - PLL IC/10.35MHz TCXO (EOL): MB15F63/MO-0365 to LMX2485/MO-0373
 - 1st MIX IC: UPC2757(EOL) to MAX2681 + added two buffer IC BGA2802 to gain adjust.
 - 1st Local OSC MIX Dual Transistor: UPA800T (EOL) to BFS483

Regards,



Paul Roby
Manager, Regulatory and Quality
Uniden America Corporation