

INTERTEK TESTING SERVICES

Report No.: 0405087
Model No.: B5881

hp

Pursuant to FCC Part 15 Section 15.241 Emissions Requirements

MKR -26.0 KHz


REF -30.0 dBm

AT 10 dB

-20.19 dB

PEAK
LOG
10
dB/

VA SB
SC LC
CORR



Tested By:

[Signature]

Date: 13-4-04

Checked By:

[Signature]

Date: 13/4/2004

Test Result: Pass / Fail / NA

CENTER 433.3575 MHz

#RES BW 10 KHz

VBW 10 KHz

SPAN 200.0 KHz

#SWP 100 msec