









Mainboard: HT862E












(Built-in Battery: GO2/MLP284154 )




(Built-in Battery: L0707-LF):



(Built-in Battery: 304055 )












**Electrostatic discharge improvement plan:**





**Mainboard: LM48511**












**Mainboard: HT862E**



**(Built-in Battery: GSP383555 01):**





END OF REPORT