



捷聯電子股份有限公司

Top Victory Electronics (Taiwan) Co., Ltd.

18F, No. 738, Chung-Cheng Rd., Chung-Ho, Taipei Hsien, Taiwan 臺北縣中和市中正路738號18樓 TEL: 886-2-82261668 FAX: 866-2-82261666

Federal Communications Commission

Authorization and Evaluation Division

7435 Oakland Mills Rd. Columbia, MD. 21046

Date: Oct. 15, 1999

Attention : Authorization and Evaluation Division

Subject : RFI related modifications incorporated into unit with - FCC ID: ARSCM569P

Dear Sirs:

This letter serves as our declaration that all modifications listed below were implemented in the sample submitted for testing. We further declare that the same modifications will be implemented into all production units to enhance compliance of the units to FCC limits.

The modifications include the following :

- 1) Added two ferrite cores on the video cable - one outside and one inside of the monitor. (see photo 2 & 5)
- 2) Added a metal cover on the rear side of CRT board and it was connected to chassis by four ground wires. (see photo 5 & 6)
- 3) Added a ferrite core on the safety ground wire with nine turns. (see photo 8)
- 4) Added a ferrite core on the harness of focus wire and G2 wire. (see photo 8)
- 5) Added a capacitor, four resistors, and two jump wires on the solder side of main board for electrical improvement only, not for EMI. They will be built into component side after circuit relay-out. (see photo 9)
- 6) Added a capacitor on the solder side of CRT board for electrical improvement only, not for EMI. It will be built into the component side after circuit re-layout. (see photo 11)

If you have any further questions or comments regarding the above, please don't hesitate to contact Mr. Mike Su of ADT Lab. at fax No.: 886-2-2602-2943 or E-mail: mike@mail.adt.com.tw

Sincerely yours,

Frank Yang / R&D Project Manager

Top Victory Electronics (Taiwan) Co., Ltd.