



捷聯電子股份有限公司

Top Victory Electronics (Taiwan) Co., Ltd.

18F, No. 738, Chung-Cheng Rd., Chung-Ho, Taipei Hsien, Taiwan 臺北縣中和市中正路738號18樓 TEL: 886-2-82261668 FAX: 866-2-82261666

Federal Communications Commission  
Authorization and Evaluation Division  
7435 Oakland Mills Rd.  
Columbia, MD. 21046

Date: July 31, 2003

Attention: Authorization and Evaluation Division

Subject: RFI related modifications incorporated  
into unit **15" LCD MONITOR (EUT)** with - **FCC ID: ARSLM1560**

Dear Sirs:

This letter serves as our declaration that all modifications listed below were implemented in the sample submitted for testing. We further declare that the same modifications will be implemented into all production units to enhance compliance of the units to FCC limits.

The modifications include the following:

1. Added two ferrite cores on the video cable – one in the inside and one in the outside of the monitor. (see photo 2 & 6)
2. Added metal shielding on the component side of the logical board and the power board for EMI. (see photo 6)
3. Added aluminium foils on the cable connecting from logical board to OSD. (see photo 8)
4. Added aluminium foils on the cable connecting from signal cable to metal cover. (see photo 6)
5. Added 4 EMI gaskets at four corners and aluminium foils on the back LCD panel. (see photo 10)

If you have any further questions or comments regarding the above, please don't hesitate to contact Mr. Mike Su of ADT Lab. at fax No.: 886-2-2605-2943 or E-mail: [mike@adt.com.tw](mailto:mike@adt.com.tw)

Sincerely yours,

R& D Project Manager  
Top Victory Electronics (Taiwan) Co. Ltd.