EXHIBIT 3B: TUNE-UP PROCEDURE (PART 2.1033)

Section 2.1033 (c)(9):

Tune-up procedure over the power range, or at specific operating power levels.

Alcatel-Lucent's wireless UMTS **9341 RRH 40W 850 MHz** Distributed Base Station Transceiver System (850 MHz), subject of this Class II Permissive Change request under FCC ID: AS5ONEBTS-17, can not be "tuned-up" by the user. There are no user tune-up features. All tuning is performed by the manufacturer during, and as part of, the manufacturing process.