



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

December 22, 2004

RE: FCC ID: ATH2425141_ATCB002026

Attention: Desmond A. Fraser

I have a few comments on this Application. Please note that further comments may arise in response to answers provided to the questions below.

1. Please note that the SAR report has some very large power drifts associated. While you have provided a power drift plot, it would be good if an explanation of why the power drifted so much could be provided. After all, a 70+% change is quite extreme for SAR. Was this also experienced during EMC testing? How did it affect power or spurious emissions measurements during EMC testing? Providing these answers may help to understand the device and how it operates under normal conditions and gives a better understanding of the testing overall and compliance.

Dennis Ward

<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.