



Request for Additional Information for EMC Certification

Company:	EF Johnson (MFlom)	Composite Device:	Yes: <input type="checkbox"/>	No: <input checked="" type="checkbox"/>
MT#:	81407	FCC Direct Filing:	Yes: <input type="checkbox"/>	No: <input checked="" type="checkbox"/>
		Permit But Ask:	Yes: <input type="checkbox"/>	No: <input checked="" type="checkbox"/>
FCC ID:	ATH2425313	FCC Rule Part:	90	
UPN:	933B-2425313	RSS Standard:	RSS-119	
FRN:	0004201521	Class II PC/Reassessment:	Yes: <input type="checkbox"/>	No: <input checked="" type="checkbox"/>

February 5, 2009

Dear Hoosam,

Thank you for your application. In order for us to process your approval, the following must be addressed. Please provide a response in a timely manner to avoid delays or dismissals.

Technical Review:

1. The FRN listed on Form 731 is of FLOM Test Labs. It should be the applicant; in this case E F Johnson.
2. Please clarify which emission masks are being applied for each plot in the test report under the emissions mask section.

If you have any questions or concerns, please contact us.

Thank you!

Jennifer Sanchez
TCB Administrator
MET Laboratories, Inc.
tcbinfo@metlabs.com
www.metlabs.com

Admin Review By: Jennifer Sanchez
Technical Review By: Dusmantha Tennakoon

Please note that partial responses increase processing time and should not be submitted. The items indicated above must be provided before processing can continue on the above referenced application. Failure to provide the requested information in a timely manner may result in application dismissal.

Jennifer Sanchez

From: Sandy Valentine [sandyv@mfлом.com]
Sent: Tuesday, February 10, 2009 10:52 AM
To: Jennifer Sanchez
Subject: re: 81407 M. Flom - FCC/IC TCB Request for technical information for EF Johnson FCC ID: ATH2425313, IC: 933B-2425313 (p08c0005)
Attachments: d0910010.FCC.Certification.Part 90 Rev3.pdf; Answers for RT.pdf; Form 731 010609 Rev2.pdf

Hello Jennifer:

Here is the response for this RT.

Sandy Valentine

Flom Test Lab
Phone: 480 926-3100
Email: sandyv@mfлом.com
Web : www.flomlabs.com

Confidential - The information in this message is only intended for the person(s) or organization(s) to whom it is addressed. If you are not that person, please contact the sender, and destroy this copy.

----- Original Message -----

From: "Jennifer Sanchez" <jsanchez@metlabs.com>
To: "Sandy Valentine" <sandyv@mfлом.com>
Date: Thu, 5 Feb 2009 14:20:55 -0800
Subject: **81407 M. Flom - FCC/IC TCB Request for technical information for EF Johnson FCC ID: ATH2425313, IC: 933B-2425313 (p08c0005)**

Hi Sandy,

Please find attached the reviewers request for additional information.

If you have any questions, please let me know.

Thanks!

J. Sanchez

TCB Administrator

MET Laboratories, Santa Clara CA

408-207-4785 Office

408-829-1603 Cell

jsanchez@metlabs.com





Flom Test Lab
EMI, EMC, RF Testing Experts Since 1963

toll-free: (866) 311-3268
fax: (480) 926-3598
www.flomlabs.com
info@flomlabs.com

February 10, 2009

Met 81407

Answers to Met RT dated 2/5/09

1. The FRN has been revised on the 731.
2. The emissions masks B and D were used. The test report has been edited to label them correctly.