
Subject: FW: ACTION ELECTRONICS CO., LTD., FCC ID: ATI9R3VOD1023, Assessment NO.: AN05T4543, Notice#1



Exhibit-C-Test_Rep Exhibit-H-External_
ort_revised.... Photos_revi...

From: iris
Sent: Thursday, February 17, 2005 6:12 PM
To: Helen Zhao
Subject: Re: ACTION ELECTRONICS CO., LTD., FCC ID: ATI9R3VOD1023,
Assessment NO.: AN05T4543, Notice#1

Dear Helen,
Reply#1 : Bandwith at 88.3 had been revised OK. Pls find the attached
Exhibit-C-Test_Report_revised.
Reply#2 : Pls find the attached Exhibit-H-External_Photos_revised.

Best Regards,

Iris Lin

-----Original Message-----

From: Compliance Certification Services [mailto:hzhao@ccsemc.com]
Sent: Monday, February 07, 2005 5:11 PM
Subject: ACTION ELECTRONICS CO., LTD., FCC ID: ATI9R3VOD1023, Assessment
NO.: AN05T4543, Notice#1

Question #1: The test plot on page 19 of the test report shows a display
line that is more than 26dB down. Please resubmit the plot and report the
correct bandwidth at 88.3MHz.

Question #2: The external photos do not clearly show the LCD panel. Please
add one more photo to show the LCD panel.

Best Regards,
Helen Zhao

The items indicated above must be submitted before processing can continue
on the above referenced application. Failure to provide the requested
information within 30 days of the original e-mail date may result in
application dismissal and forfeiture of the filing fee. Also, please note
that partial responses increase processing time and should not be submitted.
Any questions about the content of this correspondence should be directed to
the e-mail address listed below the name of the sender.