



Clarion H O N D A

PART NO. 39540-TG7-K11
MODEL NO. PH-3709
12V NEG.GND.

MANUFACTURED COE C5B17

CODE128

K1

This device complies with part 15 of the FCC Rules.
Operation is subject to the following two conditions:
(1) This device may not cause harmful interference, and
(2) this device must accept any interference received,
including interference that may cause undesired
operation.

FCC ID: AX2QY5099

2015-03-I-000096
VICAR S.A.
AV Eusebio Ayala KM. 4.5 Asuncion Paraguay



THIS PRODUCT INCLUDES TECHNOLOGY OWNED BY
MICROSOFT CORPORATION AND CANNOT BE USED OR
DISTRIBUTED WITHOUT A LICENSE FROM MSLGP.

**Clarion Co.,Ltd. 7-2 SHINTOSHIN, CHUO-KU,
SAITAMA-SHI, SAITAMA, JAPAN.**

CODE128B



SERIAL NO. CLAECT*****

PH-3709W-A 276-1661-19 MADE IN CHINA

Clarion **H O N D A**

PART NO. 39540-TG7-K31

MODEL NO. QY-5089

12V NEG.GND.

MANUFACTURED COE C5B17

CODE128

K3

This device complies with part 15 of the FCC Rules.
Operation is subject to the following two conditions:
(1) This device may not cause harmful interference, and
(2) this device must accept any interference received,
including interference that may cause undesired
operation.

FCC ID: AX2QY5099

2015-03-I-000094
VICAR S.A.
Av Eusebio Ayala KM. 4.5 Asuncion Paraguay



THIS PRODUCT INCLUDES TECHNOLOGY OWNED BY
MICROSOFT CORPORATION AND CANNOT BE USED OR
DISTRIBUTED WITHOUT A LICENSE FROM MSLGP.

**Clarion Co.,Ltd. 7-2 SHINTOSHIN, CHUO-KU,
SAITAMA-SHI, SAITAMA, JAPAN**

CODE128B



SERIAL NO. CLAECW*****

QY-5089H-A 276-1661-22 MADE IN CHINA

Clarion **H O N D A**

PART NO. 39540-TG7-K21
MODEL NO. QY-5099
12V NEG.GND.

MANUFACTURED COE C5B17

CODE128

Manufactured under license from
Dolby Laboratories
Dolby and the double-D symbol are
trademarks of Dolby Laboratories.

K2

For DTS patents, see <http://patents.dts.com>.

This device complies with part 15 of the FCC Rules.
Operation is subject to the following two conditions:
(1) This device may not cause harmful interference, and
(2) this device must accept any interference received,
including interference that may cause undesired
operation.

FCC ID: AX2QY5099

2015-03-I-000095
VICAR S.A.
Av Eusebio Ayala KM. 4.5 Asuncion Paraguay



THIS PRODUCT INCLUDES TECHNOLOGY OWNED BY
MICROSOFT CORPORATION AND CANNOT BE USED OR
DISTRIBUTED WITHOUT A LICENSE FROM MSLGP.

**Clarion Co.,Ltd. 7-2 SHINTOSHIN, CHUO-KU,
SAITAMA-SHI, SAITAMA, JAPAN.**

CODE128B



SERIAL NO. CLAECU*****

QY-5099H-A 276-1661-20 MADE IN CHINA