



Federal Communication Commission
Authorization and Evaluation Division
7435 Oakland Mills Road
Columbia,MD 21046
USA

Applicant address: A Unit, 6th Floor, Block A, Huayuan Plot, Fenghuang 1st Industrial Zone, Fuyong Street, Shenzhen City, China

FCC ID: AYQTSC100RA

Gentlemen:

The scanner receiver equipment meets the requirements of FCC Rules,15.121(a).

This scanner receiver does not have the capability of tuning the frequencies assigned to the domestic Public Cellular Radio Telecommunications

In this circuitry, this device is not readily alterable to restore the cellular band coverage because the inventory of frequencies contained within this band is not available in the microprocessor. Also, the microprocessor is fixed soldered and not easily removable.

Therefore, since the clipping of leads; or the installation of a simple component such as a diode, resistor, or a jumper wire; or the reprogramming of any semiconductor device contained within this unit cannot be accomplished using a special access code or a personal computer; This is to certify that the conditions mandated in part 15.121 have been met. Please contact the undersigned if you have any questions or need any further information.

This scanning receiver is incapable of converting digital cellular communication transmissions to analog voice audio.

A handwritten signature in black ink, appearing to read 'Zhou Rufa'.

TTI TECH(SHENZHEN)CO.LTD
Zhou Rufa
manager