dward

From: Sent: To: Subject: Keijiro.Kumagai@jp.ul.com Sunday, September 21, 2003 10:59 PM dennisw RE: New Project: CANON INC. Bluetooth Unit(BU-10)





9-19-03 Test Setup C30218 ATCB Comm Photo.pdf (225 KB) Dear Dennis,

Please confirm following reply to your comment on 19Sep2003.

1. Since this device is for exclusive use in the Bubble Jet I80, why weren 't radiated spurious emissions performed in the host? -->This time our client request us to obtain FCC grant of this device as individual unit.

2. Please provide a separate test setup photo exhibit as required by the
FCC.
-->Please find attached "Test Setup Poto.pdf".

3. The only Bandwidth measurement for FHSS devices is the 20dB bandwidth
of 15.247 (a)(1).
Please explain what the plot on page 38 is for.
-->This page 38 is for IC application. IC requires 99% Occupied Bandwidth.
We use same data so please just use it for your reference.

I saw on the news that Hurricane hit in your country was really huge one. Are you and your family OK?

I appreciate for your cooperation.

Best Regards,

"dennisw" <dennisw@sti.net> 2003/09/20 03:29 To: <Keijiro.Kumagai@jp.ul.com> cc: Subject: RE: New Project: CANON INC. Bluetooth Unit(BU-10)

Hi Keijiro Please see comments attached Thanks Dennis

-----Original Message-----From: Keijiro.Kumagai@jp.ul.com [mailto:Keijiro.Kumagai@jp.ul.com] Sent: Thursday, September 18, 2003 6:51 PM To: dennisw Cc: susan@atcb.com Subject: RE: New Project: CANON INC. Bluetooth Unit(BU-10)

Dear Dennis,

Thank you for your speedy reply. I am looking forward to hearing from you.

Best Regards,

UL Apex Co.Ltd. 4383-326 Asama-cho Ise-shi Mie-ken 516-0021 EMC Service Head Office EMC Laboratory Keijiro Kumagai TEL: 0596-24-8116/FAX: 0596-24-8124 E-mail: Keijiro.Kumagai@jp.ul.com Home Page: www.ulapex.jp ***************************

"dennisw" <dennisw@sti.net> 2003/09/19 10:02

> To: <Keijiro.Kumagai@jp.ul.com> cc: <susan@atcb.com> Subject: RE: New Project: CANON INC. Bluetooth Unit(BU-10)

Hi Keijiro

Hurricane Isabella is causing havoc on the East Coast. The server I believe is down due to power outage. I will be reviewing this application so I will take care of making sure it gets on the ATCB server. I should have something for you Friday our time.

Thanks Dennis

-----Original Message-----From: Keijiro.Kumagai@jp.ul.com [mailto:Keijiro.Kumagai@jp.ul.com] Sent: Thursday, September 18, 2003 5:40 PM To: dennis@yosemite; dward@americantcb.com Cc: susan@atcb.com Subject: New Project: CANON INC. Bluetooth Unit(BU-10)

Dear Dennis,

Yesterday I submitted application form for CANON INC., Bluetooth Unit (FCC ID: AZDK30218). However, I forgot to submit Technical Specification. Today I tried to upload from ATCB website but I could not access to the website. Please upload attached file to ATCB website.

I appreciate for your cooperation.

Best Regards,

UL Apex Co.Ltd. 4383-326 Asama-cho Ise-shi Mie-ken 516-0021 EMC Service Head Office EMC Laboratory Keijiro Kumagai TEL: 0596-24-8116/FAX: 0596-24-8124 E-mail: Keijiro.Kumagai@jp.ul.com Home Page: www.ulapex.jp ***************************

Dear Dennis,

Today, I submitted application documents for CANON INC., Bluetooth Unit (FCC ID: AZDK30218). Please confirm and let me know if there is any missing documents or information.

Also please issue invoice for this project.

I truly appreciate for your cooperation.

Best Regards,

UL Apex Co.Ltd. 4383-326 Asama-cho Ise-shi Mie-ken 516-0021 EMC Service Head Office EMC Laboratory Keijiro Kumagai

-- For more information about UL, its Marks, and its services for EMC, quality registrations and product certifications for global markets, please access our web sites at http://www.ul.com and http://www.ul-asia.com, or contact your local sales representative. --

******** Internet E-mail Confidentiality Disclaimer *********

This e-mail message may contain privileged or confidential information. If you are not the intended recipient, you may not disclose, use, disseminate, distribute, copy or rely upon this message or attachment in any way. If you received this e-mail message in error, please return by forwarding the message and its attachments to the sender.