



APPENDIX B-Page 1 of 5 Tel: +886 2 26099301 Fax: +886 2 26099303

B.2 Radiated Measurement at Chamber

Frequency Below to 1GHz Ant 1-Black (ANTB24-104A0)



Zoom View




File Number: C1M2209041 This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.




APPENDIX B-Page 2 of 5 Tel: +886 2 26099301 Fax: +886 2 26099303

Ant 2-Gray (UFL-LP6-068N1T-A11-T-153D)



Zoom View



File Number: C1M2209041 This test report may be reproduced in full only. The document may only be updated by Audix Technology

Corp. personnel. Any changes will be noted in the Document History section of the report.




AUDIX Technology Corp. No. 491, Zhongfu Rd., Linkou Dist., New Taipei City244, Taiwan

APPENDIX B-Page 3 of 5 Tel: +886 2 26099301 Fax: +886 2 26099303

Frequency Above to 1GHz Ant 1-Black (ANTB24-104A0)



Zoom View




File Number: C1M2209041 This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.




APPENDIX B-Page 4 of 5 Tel: +886 2 26099301 Fax: +886 2 26099303

Ant 2-Gray (UFL-LP6-068N1T-A11-T-153D)



Zoom View




File Number: C1M2209041 This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.



APPENDIX B-Page 5 of 5 Tel: +886 2 26099301 Fax: +886 2 26099303

B.3 RF Conducted Measurement



File Number: C1M2209041

Report Number: EM-F220718

This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.