



APPENDIX B-Page 1 of 4 Tel: +886 2 26099301 Fax: +886 2 26099303

B.2 Radiated Measurement at Chamber

Frequency Below to 1GHz Test Model: R7206SB



Test Model: R7306SB



File Number: C1M2305051

Report Number: EM-F230326


This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.



APPENDIX B-Page 2 of 4 Tel: +886 2 26099301 Fax: +886 2 26099303

Frequency Above to 1GHz

Test Model: R7206SB



Test Model: R7306SB



File Number: C1M2305051

Report Number: EM-F230326

This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.




No. 491, Zhongfu Rd., Linkou Dist., New Taipei City244, Taiwan


APPENDIX B-Page 3 of 4 Tel: +886 2 26099301 Fax: +886 2 26099303

EUT View In

Test Model: R7206SB



Test Model: R7306SB



File Number: C1M2305051


Report Number: EM-F230326

This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.



APPENDIX B-Page 4 of 4 Tel: +886 2 26099301 Fax: +886 2 26099303

B.3 RF Conducted Measurement



File Number: C1M2305051

Report Number: EM-F230326

This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.