

## Suite 200 1400 West Stanford Ranch Road Suite 200 Rocklin, CA, 95765 United States

Federal Communications Commission 7435 Oakland Mills Road Columbia MD 21046

Attention: Application Examiner / Review Engineer

Subject: Request to change identification per section 2.933 of FCC rules

Date: 2021-08-13

Reference: FCC ID: B32E135(new FCC ID)

To The Commission:

This Change of Identification request applies for a new FCC ID: B32E135 as established in 47CFR 2.933(b) for a currently approved device. This application by VERIFONE INC will establish a new FCC ID under (2AB7X) grantee code for purpose of marketing. The original grant to FCC ID: 2AB7X-WISEPAD3(original ID) will remain in effect.

An authorization letter by BBPOS International Limited is attached. Per 2.933(b)

- 1. The original identification is FCC ID: 2AB7X-WISEPAD3
- 2. The original grantee date is

02/27/2021(DTS)

02/27/2021(DSS)

02/27/2021(DXX)

- 3. The equipment is electrically identical. Only the FCC ID number and model number and product name are different.
- 4. The original test results are application and representative of this changed device.
- 5. Exterior photographs are included in this application.

This following files are electronically submitted as attachments:

Cover Letter

External Photos

FCC ID label format and location

Sincerely yours,

Steve Hsu / Sr. Director, Hardware Engineering

Verifone, Inc.

Tel.: 886-3789-7313 Fax: 886-2-26553168

E-mail: Steve\_H@VERIFONE.com