

Date: March 23, 2020

SUBJECT: Supersede for FCC ID: B32M424, Granted Date: 03/11/2020

To Whom It May Concern:

We, **VeriFone Inc**, would like to supersede Internal Photos and External Photo, Since the power supply photo is not correct in the file, modification is needed.

The superseded documents are listed as below:

Original File name	Newly File name
External Photos	External Photos rev
Internal Photos	Internal Photos rev

Should you have any question or comment regarding this matter, please do not hesitate to contact me.

Sincerely yours,

Steve Hsu / Sr. Director, Hardware Engineering

Verifone, Inc.

Tel.: +886-3789-7313

E-mail: steve_h@verifone.com