



M. Flom Associates, Inc. - Global Compliance Center

3356 North San Marcos Place, Suite 107, Chandler, Arizona 85225-7176

www.mflom.com general@mflom.com (480) 926-3100, FAX: 926-3598

Date: March 26, 2001

Federal Communications Commission
Via: Electronic Filing

Attention: Andy Leimer
Authorization & Evaluation Division

Applicant: Telex Communications, Inc.
FCC ID: B5DM514
EA99922
Reference: Correspondence Number 18486

Mr. Leimer:

1) The correct band of operation for this device is 518 - 608 MHz. Please see the General Description paragraph 2 of the Owner/User's Manual.

This is your authorization to revise paragraph 8(a) of Form 731 accordingly.

2) Please find uploaded today into the RF Exposure Exhibit a) Calculated MPE Report and b) RF Exposure information which will be amended in the User's Manual.

We trust this meets the requirements of the Commission and the Grant will be issued shortly.

Sincerely yours,

A handwritten signature in black ink that reads 'Morton Flom, P. Eng.' The signature is written in a cursive, somewhat stylized script.

Morton Flom, P. Eng.

enclosure(s)
cc: Applicant
MF/cvr