


Test Of: Ericsson AB
RBS 2308 1900 MHz
To: FCC Part 24: 2003


PHT/71622JD11/011 RRU-M19 EDGE. Back View



Test Of: Ericsson AB
RBS 2308 1900 MHz


To: FCC Part 24: 2005

PHT/71622JD11/012 RRU-M19 EDGE. Open View




Test Of: Ericsson AB
RBS 2308 1900 MHz
To: FCC Part 24: 2003

PHT/71622JD11/013 Digital Radio Access Board 1. Front View




Test Of: Ericsson AB
RBS 2308 1900 MHz
To: FCC Part 24: 2005

PHT/71622JD11/014 Digital Radio Access Board 1. Back View




Test Of: Ericsson AB
RBS 2308 1900 MHz
To: FCC Part 24: 2003

PHT/71622JD11/015 Digital Radio Access Board 2. Front View




Test Of: Ericsson AB
RBS 2308 1900 MHz
To: FCC Part 24: 2005

PHT/71622JD11/016 Digital Radio Access Board 2. Back View



Test Of: Ericsson AB
RBS 2308 1900 MHz
To: FCC Part 24: 2003

PHT/71622JD11/017 Duplex Filter 1. Front View



Test Of: Ericsson AB
RBS 2308 1900 MHz
To: FCC Part 24: 2005

PHT/71622JD11/018 Duplex Filter 1. Back View

