



**警告 WARNING**

送信機のチャンネル変更は、無誤チャンネルの管理員(施設管理員)の責任下において行ってください。誤った運用は、患者を誤り通えるなどの重大な事故を引き起こすおそれがあります。施設管理員は必ず以下のことを行ってください。

- 施設内で使用しているすべてのチャンネルを把握し、チャンネル変更による誤通の発生を防止してください。
- チャンネル変更後、受信モニターで変更後のチャンネルで確実に受信できることを確認してください。
- チャンネル変更する場合は、送信機のチャンネル銘板を貼り替えてください。また、必要に応じてフーンラベルも貼り替えてください。

The following action must be taken to properly receive the transmitter signal of the correct patient on the receiving instrument. Otherwise, there may be signal loss or signals may mix causing a serious accident, such as monitoring a different patient.

- Assign a channel administrator in the hospital and only he or she should manage channel assignment on his or her responsibility.
- The channel administrator must manage the channels in the facility so that there is no signal interference.
- When the transmitter channel is changed, the channel administrator must check that the channel on the receiving monitor is also changed and the signal is properly received.
- The channel administrator must replace the channel number label on the transmitter with the new one after changing the channel.

NIHON KOHDEN

POWER



SERIAL



CHANNEL WRITER







NihonKoden  
FCC ID LABEL AREA  
04I2957 9/10

CD -264P  
00201 AC



NIHON KOHDEN  
**検査合格証**  
日本光電



21

22

5/8

23

24

25

26

27

3/4

28

29

30

31

7/8





Nihon Kohden  
ECC ID LABEL AREA  
0452957 9/10

NIHON KOHDEN  
検査合格証  
日本光電

CHANNEL WRITER


SERIAL

POWER

NIHON KOHDEN







**警告 WARNING**

送信機の子ナレ風量は、無誘子ナレの管理員(施設管理員)の責任下において行うべきであり、無誘子ナレは、患者を引渡さるなどの重大な事故を引き起こす可能性があります。施設管理員は以下のことを行ってください。

- 施設内で使用しているすべての子ナレを確認し、子ナレが変更による送信機との発生を防止してください。
- 子ナレの風量、送信機の子ナレの風量を必要に応じて変更できることを確認してください。
- 子ナレの変更する場合は、送信機の子ナレの風量を引上げてください。また、設置した子ナレの風量を引上げてください。

The following action must be taken to properly receive the transmitter signal of the correct patient on the receiving instrument. Otherwise, there may be signal loss or signals may mix causing a serious accident, such as monitoring a different patient.

- Assign a channel administrator in the hospital and only he or she should manage channel assignment on his or her responsibility.
- The channel administrator must manage the channels in the facility as he then is to signal interference.
- When the transmitter channel is changed, the channel administrator must check that the channel on the receiving monitor is also changed and the signal is properly received.
- The channel administrator must replace the channel number label on the transmitter with the new one after changing the channel.

Q1 -901P  
00149 AC

チャンネルライタ  
型名 Q1-901PK 5V ≡ 500mA  
製造番号 00149

販売 日本光電工業株式会社  
製造 日本光電富田株式会社 東京都新宿区西落合1-31-4





**▲ 警告 WARNING**

送信機と受信機は、同じチャンネルを同時に使用して通信を行うことができません。また、送信機は、受信機が受信しているチャンネルに干渉を及ぼす可能性があります。受信機が受信しているチャンネルに干渉を及ぼす可能性があります。

- 送信機で使用しているチャンネルと受信機が受信しているチャンネルが同じチャンネルである場合は、送信機と受信機が同時に通信を行うことができません。
- 送信機と受信機、送信機と送信機、受信機と受信機が同じチャンネルを使用している場合は、送信機と受信機が同時に通信を行うことができません。

The following action must be taken to properly receive the transmitter signal of the correct channel on the receiving equipment. Otherwise, there may be signal loss or signal may not cause a correct action, such as receiving a different packet.

- Assign a channel administrator in the Apptela and only he or she should manage channel assignment on his or her responsibility.
- The channel administrator must manage the channels in the Apptela so that there is no signal interference.
- When the transmitter channel is changed, the channel administrator must check that the channel on the receiving receiver is also changed and the signal is properly received.
- The channel administrator must receive the channel number and the channel administrator will be able to change the channel on the transmitter with the new one after changing the channel.





送信機のチャネル変更は、無線チャネルの管理者(統括管理者)の責任下において行ってください。誤った運用は、患者を取り返さるなどの重大な事故を引き起こすおそれがあります。統括管理者は必ず以下のことを行ってください。

- 施設内で使用しているすべてのチャネルを把握し、チャネル変更による誤信などの発生を防止してください。
- チャネル変更後、受信モニタで変更後のチャネルで確実に受信できることを確認してください。
- チャネル変更をする場合は、送信機のチャネル銘板を貼り替えてください。また、必要に応じてノックアウトも貼り替えてください。

The following action must be taken to properly receive the transmitter signal of the correct patient on the receiving instrument. Otherwise, there may be signal loss or signal loss of signal.


- Assign a channel administrator in the hospital and only he or she should manage channel assignment on his or her responsibility.
- The channel administrator must manage the channels in the facility so that there is no signal interference.
- When the transmitter channel is changed, the channel administrator must check that the channel on the receiving monitor is also changed and the signal is properly received.
- The channel administrator with the new one after changing the channel on the transmitter must replace the channel number label

警告 WARNING

ZS-900P







737-001B S/N 03100132

CHANNEL WRITER

737-001B

AL M alto

OMRON XM2C-0912 2G08

H8/3067  
HD 3H4 R  
64F3067F20  
JAPAN

4069UBF  
0333 HC

8.000124

2A4KSS3BT

JST

737-001B S/N 03100132