HP Inc.

3390 East Harmony Road

Fort Collins 80528 Colorado United States

Federal Communications Commission 7435 Oakland Mills Road - Gate A Columbia, Maryland 21046

Date: April 20, 2018

Attention: Application Examiner / Review Engineer

Subject: Request to change in identification per section 2.933 of FCC rules

Reference: FCC ID: B94-8265D2WB

To The Commission:

This Change of Identification request applies for a **new** FCC ID: **B94-8265D2WB** as established in 47CFR 2.933(b) for a currently approved device. This application by **HP Inc.** will establish a new FCC ID under **B94** grantee code for purpose of marketing. The original grant to **PD98265D2** will remain in effect.

An authorization letter by **Intel Mobile Communications** is attached. Per 2.933(b)

- 1. The original identification is **PD98265D2**
- 2. The original grant date is 06/28/2016
- 3. The equipment is electrically identical. Only the FCC ID number is different.
- 4. The original test results are applicable and representative of this changed device.
- 5. Exterior photographs are included in this application.

The following files are electronically submitted as attachments:

Cover Letter

External Photos

FCC ID label format and location

Sincerely yours,

Richard P Tarsio / US Canada Technical Regulations

Richard P Tarsio

HP Inc.

Tel: 970-898-8713 Fax: 000-000-0000

E-mail: richard.tarsio@hp.com