


Appendix C – SAR Test Setup Photos



Test Position Back 0 mm Gap

Note: All cables are removed prior to testing.





Test Position Top 0 mm Gap

Note: All cables are removed prior to testing.






Test Position Right 0 mm Gap

Note: All cables are removed prior to testing.





Front of Device Tablet Mode





Back of Device Tablet Mode





Laptop Mode