



American Certification Body
6731 Whittier Avenue Suite C110
McLean, VA 22101
USA

Date: 9/21/2019

Ref: Application for Original Equipment Authorization for FCC ID: B94-HNC04PKCP2

Dear Examiner,

This is to request to dismiss grants issued under FCC ID: B94-HNC04PKCP2.

This FCC ID was in error and will be superceded by FCC ID: B94HNC04PKCP2.
The error was a typo that inserted a (-) into the ID by mistake. All other documents
are correct.

TC Numbers are as follows: TC972141, TC784385, TC700109, TC625828 and
TC761014.

The product bearing the FCC ID/TCs in question have not been marketed or sold
anywhere in the United States nor anywhere in the world.

Sincerely,

A handwritten signature in black ink, appearing to read 'Steven C. Hackett'.

Steven C. Hackett

Sr Regulatory Engineer, Intel Corporation acting as agent on behalf of HP Inc. 1501
Page Mill Road Palo Alto, CA 94304