



HP Inc.  
3390 East Harmony Road  
Mailstop 66  
Fort Collins, CO 80528

hp.com

Federal Communications Commission  
7435 Oakland Mills Road  
Columbia, MD 21046

Certification and Engineering Bureau  
ISED Canada  
3701 Carling Avenue (Building 94)  
Ottawa, Ontario  
K2H 8S2

Date: 2021-07-12  
Subject: Request to change in Identification

To Whom It May Concern:

This application for Change of Identification request a new FCC ID as stipulated in 47 CFR 2.933 (b) for presently authorized equipment.

This application by HP Inc. will establish a new FCC ID: B94-PF002  
a new IC: 466C-PF002, PMN: HyperX Pulsefire Haste Wireless Mouse,  
HVIN: PF002, FVIN: N/A for the purpose of marketing.

The original grant to Kingston Technology Company  
FCC ID: JIC-PF002, IC: 3880A-PF002, PMN: HyperX Pulsefire Haste Wireless Mouse,  
HVIN: PF002, FVIN: N/A will remain in effect.

Per 47 CFR 2.933 (b)

- 1) The original identification is JIC-PF002
- 2) The original grant date is 4/8/2021
- 3) The equipment is electrically and functionally identical. Only the applicant, label, and FCC ID number are different.
- 4) The original test results are applicable and representative of this change ID device.
- 5) Exterior photographs are included in this application.

Sincerely,

By: Vanessa Tsai  
(Signature)

Vanessa Tsai / Product Compliance Engineer  
(Print name / Title)