

HP Inc.

3390 East Harmony Road
Fort Collins 80528 Colorado United States

Federal Communications Commission
7435 Oakland Mills Road - Gate A
Columbia, Maryland 21046

Date: **June 27, 2019**

Attention: Application Examiner / Review Engineer

Subject: Request to change in identification per section 2.933 of FCC rules

Reference: **FCC ID: B94-AX201D2WR**

To the Commission:

This Change of Identification request applies for a **new** FCC ID: B94-AX201D2WR as established in 47CFR 2.933(b) for a currently approved device. This application by **HP Inc.** will establish a new FCC ID under **B94** grantee code for purpose of marketing. The original grant to **PD9AX201D2** will remain in effect.

An authorization letter by **Intel Mobile Communications** is attached.
Per 2.933(b)

1. The original identification is **PD9AX201D2**
2. The original grant date is **11/20/2018**
3. The equipment is electrically identical. Only the FCC ID number is different.
4. The original test results are applicable and representative of this changed device.
5. Exterior photographs are included in this application.

The following files are electronically submitted as attachments:

Cover Letter

External Photos

FCC ID label format and location

Sincerely yours,

Name: Peter S. Tevlin	Email: peter.tevlin@hp.com Telephone: +1 512 319 7260
Signature:	
Title: Regulatory Manager, Communications Modules, Worldwide Technical Regulations On behalf of Company: HP Inc. 1501 Page Mill Road Palo Alto, CA 94304	